





Replaces the recommendation SIA 162/5, 1997 edition, and Appendix A of Technical Specification SIA 2018, 2004 edition

Erhaltung von Tragwerken – Betonbau Maintenance des structures porteuses – Structures en béton Conservazione delle strutture portanti – Costruzioni in calcestruzzo

# **Existing structures – Concrete structures**



Reference number SN 505269/2:2011 en

Valid from: 2011-01-01

Number of pages: 44

Published by Swiss Society of Engineers and Architects P.O. Box, CH-8027 Zurich

Any corrections to and comments on this publication can be found at www.sia.ch/korrigenda.

The SIA assumes no liability for any damages which might be caused through the application of this publication.

2016-09 1<sup>st</sup> Edition

## CONTENTS

### Page

Foreword 4			
0	Scope	5	
0.1	Limitations	5	
0.2	References	5	
0.3	Deviations	6	
1	Terminology	7	
1.1	Technical terms	7	
1.2	Symbols	9	
2	Basic principles	12	
2.1	General	12	
2.2	Examination	12	
3	Construction materials	13	
3.1	General	13	
3.2	Concrete	13	
3.3	Reinforcing steel	14	
3.4	Prestressing steel	15	
4	Structural analysis and verifications	16	
4.1	General	16	
4.2	Examination value	17	
4.3	Verification of structural safety	17	
4.4	Verification of serviceability	18	
4.5	Special considerations	19	
5	Condition survey	23	
5.1	General	23	
5.2	Inspection methods	23	
6	Condition evaluation	25	
6.1	General	25	
6.2	Deterioration as a result of		
	alkali-aggregate reaction	25	
6.3	Deterioration as a result of corrosion		
	of the reinforcement	26	
6.4	Prediction of the development of the		
	condition	26	
7	Interventions	27	
7.1	General	27	
7.2	Basic principles and methods	27	
7.3	Strengthening	30	
7.4	Methods	31	
7.5	Requirements applicable to the products	-	
	and systems	35	
7.6	Quality assurance	35	

## Appendix

# A Construction material properties (normative) 37 B Structural measures (normative) 40 C Determinations of the crack width index (normative) 41

Page

## FOREWORD

Code SIA 269/2 describes the procedures to be followed in the preservation of concrete structures and is directed at specialists in the preservation of structures. It is also addressed to owners of structures as well as specialists involved in construction management and the execution of construction work.

Code SIA 269/2 forms part of the SIA's structural codes relating to existing structures and is supplemented by the following codes:

- Code SIA 269 Existing structures Bases for examination and interventions
- Code SIA 269/1 Existing structures Actions
- Code SIA 269/3 Existing structures Steel structures
- Code SIA 269/4 Existing structures Composite steel and concrete structures
- Code SIA 269/5 Existing structures Timber structures
- Code SIA 269/6 Existing structures Masonry structures
- Code SIA 269/7 Existing structures Geotechnics.

Technical Specification SIA 2018 continues to apply to the examination of existing buildings with respect to earthquakes. However, it is planned to supplement the codes for existing structures with a Code SIA 269/8 *Existing structures – Seismic aspects*.

Code SIA 269/2 addresses various aspects concerning existing concrete structures that are not covered by Codes SIA 262 and 262/1.

Codes SIA 269 Project Management Team and Working Group SIA 269/2

Abbreviations of organisations represented in the commission SIA 262

Empa	Swiss Federal Laboratories for Materials Science and Technology
EPFL	Swiss Federal Institute of Technology, Lausanne
ETH Zürich	Swiss Federal Institute of Technology, Zurich
FEDRO	Federal Roads Office

### **Project Management – Codes for Existing Structures**

Dr. Paul Lüchinger, dipl. Ing. ETH, Zurich (chairman) Prof. Dr. Eugen Brühwiler, dipl. Ing. ETH, Lausanne Thomas P. Lang, dipl. Ing. ETH, Berne Prof. Thomas Vogel, dipl. Ing. ETH, Zurich

#### Working Group SIA 269/2 Existing structures – Concrete structures

Dr. Luc Trausch, dipl. Ing. ETH, Zurich (chairman) Ruedi Gall, dipl. Ing. HTL, Chur Prof. Dr. Albin Kenel, dipl. Ing. ETH, Rapperswil-Jona Dr. Heidi Ungricht, dipl. Ing. ETH, Chur Prof. Dr. Daia Zwicky, dipl. Ing. ETH, Freiburg

#### Commission SIA 262 "Concrete structures"

President	Prof. Thomas Vogel, dipl. Ing. ETH, Zurich	ETH Zürich
President Members	Prof. Thomas Vogel, dipl. Ing. ETH, Zurich Dr. Manuel Alvarez, dipl. Ing. ETH, Berne Daniel Buschor, dipl. Ing. ETH, Burgdorf Aldo Chitvanni, dipl. Ing. ETH, Chur Christoph Czaderski, dipl. Ing. ETH, Dübendorf Nicola Guidotti, dipl. Ing. ETH, Bellinzona Ernst Honegger, dipl. Ing. ETH, Wildegg Dr. Bernard Houriet, dipl. Ing. ETH, Tramelan Dr. Fritz Hunkeler, dipl. Ing. ETH, Wildegg Prof. Dr. Albin Kenel, dipl. Ing. ETH, Rapperswil-Jona Martin Knecht, Cornaux Dr. Peter Lunk, dipl. Ing. ETH, Zurich Prof. Dr. Aurelio Muttoni, dipl. Ing. ETH, Lausanne Erdjan Opan, dipl. Ing. ETH, Neuenburg Dr. Luc Trausch, dipl. Ing. ETH, Zurich	ETH Zürich FEDRO Consulting Engineer Empa Administration Industry Consulting Engineer Material Testing Univ. of Applied Sciences Industry Industry Consulting Engineer EPFL/Consulting Engineer Consulting Engineer/Construction Management Consulting Engineer

## Approval and validity

The SIA's central committee for codes and regulations approved the present Code SIA 269/2 on 23rd November 2010.

It is valid as from 1<sup>st</sup> January 2011.

It replaces the recommendation SIA 162/5 *Maintenance of concrete structures*, 1997 edition, and Appendix A of the Technical Specification SIA 2018 *Examination of existing buildings with respect to earthquake*, 2004 edition.

All rights are reserved, including the right to print extracts, partial or full reproduction (photocopy, microcopy, CD-ROM, etc.), storage in data processing systems and translation.

Copyright © 2011 by SIA Zurich